



Fermilab
ES&H Section

INDUSTRIAL HYGIENE EQUIPMENT PROCEDURES

APPLIED MAGNETICS GAUSSMETER

9/92

PURPOSE

To provide guidance in the use of the Applied Magnetics Gaussmeter.

DISCUSSION

The Applied Magnetics Laboratory GM1A is a Hall effect magnetic field meter suitable for surveys of expected field strengths from 3 - 20,000 gauss. Due to poor ergonomic design, however, it needs frequent rezeroing. Rezeroing is required if, while performing a survey, your readings become erratic or nonsensical, or, if rough handling of the device causes one of the dials to move.

MATERIALS

- AML GM1A with a PT20 probe.
- Pen, pencil, and calculator
- Sampling Notes form.

PROCEDURE

1. Calibration
 - a. Zeroing and calibration should be done in a place relatively free of manmade magnetic fields (in most cases, outside).
 - b. Turn on the **FINE** control knob to mid-rotation. This turns the unit on.
 - c. If the **BAT** indicator appears (upper left of display), replace the battery.
 - d. Press the **RUN/20K** button. Allow the unit a few seconds to stabilize. *Assure that the probe will not move during calibration.* Adjust the

OFFSET dial until the display reads **0.00** unless the display shows under 0.05 Gauss.

- e. Press the **2K** button and adjust the **COARSE** dial until the display reads **000**.
 - f. Press the **200** button and very carefully adjust the **FINE** dial until the display reads between - **01.0 and 01.0** . This level of zeroing is sufficient for measuring fields greater than 100 Gauss.
 - g. Press the **20** button. Note the reading on the display. If the meter reads outside the range between - **1.00 and 1.00**., carefully adjust the **FINE** dial to bring it in this range. This level of zeroing is sufficient for measuring fields greater than 10 Gauss or for quick checks of fields greater than 4 Gauss.
 - h. Press **INT. CAL.** . Allow 5 seconds for display to stabilize. Adjust the "**CAL**" control (small hole, upper right of case) with a small screwdriver so that the display value is equal to the calibration number written on the probe (under the Model No.).
 - i. Select the **2K** range to verify that display returns to zero. If necessary, re-zero display and repeat the sequence.
 - j. Record that the unit was calibrated on the Sampling Notes form.
 - k. To turn off, press **STOP**.
2. Measurement Techniques
- a. When you are ready to take measurements, press the **RUN/ 20K**. Select the desired sampling range.
 - a. Remember that a Hall probe is very directional and the sensing area is very small compared to the overall dimensions of the probe.
 - b. When making measurements, the peak reading will be obtained by rotating the probe in the field, in addition to simply moving the probe around.
 - c. You are looking at a very small area with each measurement. You may see large variations in field strength with very little physical movement of the probe. You may have to take quite a few measurements to completely describe the magnetic field.
3. When the survey is completed, turn the meter off with the **FINE** control dial. Return the unit to the ES&H Section. Send a completed Sampling Notes form to the ES&H Section.

